FROM LEAKING ROOF TO LIVING ROOF



New Prayer Room and Meeting Room: WATER EATON CHURCH CENTRE


FROM BROKEN BRICKS AND TIRED WALLS



New Prayer Room and Meeting Room: WATER EATON CHURCH CENTRE

POOR QUALITY ACCESS TO THE GARDEN




MOULD & ROT


PEELING BACK THE LAYERS


WINDOWS OUT


WINDOWS DISCOVERED


ROOF OFF


ROOF ON

FROM LEAKING ROOF TO LIVING ROOF



New Prayer Room and Meeting Room: WATER EATON CHURCH CENTRE



LIVING ROOF



New Prayer Room and Meeting Room: WATER EATON CHURCH CENTRE



New Prayer Room and dedicated access to the garden






PRAYER ROOM


MEETING ROOM


FOOTPATH
CLOSED
AHEAD